



Temperature correction factor for bursting pressure	-20°C	0°C	+23°C	+30°C	+40°C	+50°C	+60°C	+70°C
	1,87	1,4	1	0,84	0,7	0,6	0,52	0,47

Hardness: 98 ShA / 52 ShD.

Working temperature: From -30°C to +80°C.

Material: Polyurethane: PU type

ØD1	Working Pressure (bar)	Working pressure (psi)	Burst pressure (bar)	Burst pressure (psi)	Bending radius (mm)	
2x4 mm	15	217,5	60	870	11	25
4x6 mm	10	145	40	580	18	25
6x8 mm	7	101,5	28	406	35	25
8x10 mm	5,5	79,75	22	319	45	25
9x12 mm	7	101,5	25	362,5	50	25
2,5x4 mm	10	145	40	580	15	100
4x6 mm	10	145	40	580	18	100
6x8 mm	7	101,5	28	406	35	100
6,5x10 mm	10	145	40	580	30	100
8x12 mm	7	101,5	28	406	50	100