


Straight bulkhead adaptor without nuts (60°)

Carbon steel



| R1        | R2        | L    | HEX 1 | ØC   |
|-----------|-----------|------|-------|------|
| 1/4" BSP  | 1/4" BSP  | 49   | 19    | 6    |
| 3/8" BSP  | 3/8" BSP  | 54   | 22    | 8    |
| 1/2" BSP  | 1/2" BSP  | 60,5 | 27    | 11   |
| 3/4" BSP  | 3/4" BSP  | 66   | 32    | 16   |
| 1" BSP    | 1" BSP    | 75   | 41    | 22   |
| 1"1/4 BSP | 1"1/4 BSP | 81   | 50    | 28,5 |
| 1"1/2 BSP | 1"1/2 BSP | 88   | 55    | 33   |