



Adjustable stud branch TEES with o'ring**1/1**

ØD1	Serie	Working Pressure (bar)	L	L1	HEX 1	HEX 2
6	L	500	19	24	12	14
8	L	500	21	25,5	12	17
10	L	500	22	29	14	19
12	L	400	24	29,5	17	22
15	L	400	28	31	19	27
18	L	315	31	34	24	32
22	L	250	35	37,5	27	36
28	L	250	38	41,5	36	41
35	L	250	45	48	41	50
42	L	160	51	52	50	60
6	S	630	23	25	12	17
8	S	630	24	26	14	19
10	S	630	25	29	17	22
12	S	630	29	30	17	24
14	S	630	30	31	19	27
16	S	420	33	33,5	24	30
20	S	420	37	41,5	27	36
25	S	420	42	47	36	46
30	S	420	49	55	41	50
38	S	315	57	56,5	50	60